

2022 PHRF-NB Membership/Rating Certificate

This certificate expires on April 30, 2023, or upon change of ownership, whichever comes first.

Certificate status: Renewed

Ratings

| | |
|-----------|---------------|
| 222 | 244 |
| Spinnaker | Non-Spinnaker |

Administrative Data

| | |
|-------------------------|-------------------------|
| Name: | Forzati, Kenneth T. Jr. |
| Address: | Privacy Protected |
| Email: | |
| Primary Phone: | |
| Secondary Phone: | |
| Yacht Club: | RIYC |

Yacht

| | |
|--|---------------------------------|
| Yacht Name: Girasole | Sail Number: 514 |
| Designer: CR Hunt, Assoc | |
| Manufacturer: Bangor Punta Marine | Model: O'Day 28 (441>) K |
| Hull Serial Number: XDY514M84F | Date Manufactured: 1984 |
| Other Ratings: | Date Last Rated: |

Boat Measurements

| | | |
|--|----------------------------|------------------------|
| I: 36 | J: 12.08 | LOA: 28.25 |
| P: 30.5 | E: 10 | LWL: 22.92 |
| ISP: 36 | SPL: 12.08 | Draft: Max 4.67 |
| Py: | Ey: | |
| Beam: 10.25 | Displacement: 7300 | |
| Rig Type: Sloop | Rig: Masthead | |
| Keel Weight: 2550 | Keel Material: Lead | |
| Composite Rigging: no | Other Ballast: | |
| Mast Material: Aluminum | Spinnaker Type(s): | |
| Asymmetrical Spinnaker Tacked To: | | |

Sails

| Headsails to be used (LP%) | | Mainsail Measurements | |
|----------------------------|-----|-----------------------|--|
| Headsail 1 | 135 | MHB | |
| Headsail 2 | 0 | MUW | |
| Headsail 3 | 0 | MTW | |
| Headsail 4 | 0 | MHW | |
| | | MQW | |

Spinnakers to be used

| Spin # | JC | SMG | Foot | Luff | Leech |
|---------------|----|-----|------|------|-------|
| Spin 1 | | | | | |
| Spin 2 | | | | | |
| Spin 3 | | | | | |
| Code 0 | | | | | |

Headsail Credit: Cruising Headsail

Variables

| | |
|-------------------------------------|--------------------------|
| Engine: Inboard | Prop. Type: Solid |
| Prop. Install: Exposed Shaft | Rudder: Spade |
| # of Blades: 2 | Keel: Fin Keel |

Comments/Modifications

2007:Mast step was rebuilt increasing mast height by approx. 1in from the std dimension listed above. This also necessitated the use of an extender plate on the backstay = No change in rating. 2009:rudder replaced = no change in rating. Revision #1. Form not calculating correctly. Corrected rating and re-issued cert.
2021-No spin onboard.
2022- No changes.

Committee Use Only

| PHRF #: 16582 | | | |
|----------------------------|-------------|----------------------------|----|
| Base Rating | 204 | Non-Spin Adj. | 22 |
| Genoa Spin Adj. | 6 | Genoa Non-Spin Adj. | 6 |
| Mainsail Adj. | 0 | Furling Adj. | 6 |
| Spin. Area Adj. | 0 | Whisker Pole Adj. | 0 |
| Prop. Adjustment | 6 | | |
| Mast Adj. | 0 | Misc. Adj. | 0 |
| Committee Signature | Date | | |
| Katherine Rotsky | 2022-05-04 | | |